

P.O. BOX 2276 SANTA CRUZ CA 95063 831.475.0143

GAS LEAK SURVEY REPORT

	Survey Date <u>8-12-15</u>
ALIMUR M.H.P 4300 SOQUEL DR SOQUEL, CA 95073	
PERSONNEL: BRETT HIXSON	
SURVEY CONDITIONS: Dry	CALM
Type of Gas:	ne
No. of Services: 146	
No. of Anodeless Risers:	

Leak Classification and Action Criteria

Grade 1	A LEAK THAT REPRESENTS AN EXISTING HAZARD TO PERSONS OR PROPERTY. REQUIRES <u>IMMEDIATE</u> REPAIR.
Grade 2	A LEAK THAT IS RECOGNIZED AS NON-HAZARDOUS AT THE TIME OF DETECTION. REQUIRES SCHEDULED REPAIR.
Grade 3	A LEAK THAT IS RECOGNIZED AS NON-HAZARDOUS AT THE TIME OF DETECTION. IF NOT REPAIRED, SHOULD BE MONITORED ANNUALLY

Equipment	Sensitivity	<u>Alarm</u>
OVA 88	1 PPM - 10% <i>Gas</i>	3 PPM
CGI	.5% - 100% <i>Gas</i>	



ABOVE GROUND LEAK REPORT

FOR	ALIMUR	M.H.P.	Date 8-12-15
-----	--------	--------	--------------

ANY GAS LEAK IS EXTREMELY DANGEROUS AND SHOULD BE REPAIRED BY A QUALIFIED TECHNICIAN IMMEDIATELY!

	%						*Flex			Date Repaired	l
Space	Gas	Grade	Riser	Valve	Reg.	Meter	Line	Union	Other	& Initial	METHOD OF REPAIR
N	0	LEA	KS	<i>)</i> -	-00	wD	A	7 7	HZS	TIME	
										-	
								1			
				* * * * * * * * * * * * * * * * * * *							

^{*} A flex line leak is the responsibility of the coach Owner.

	12	1/-	
Reported by	D.	HIXSON	